

*~ Pax Tip ~*

Never collect metal fillings and wood sawdust in the same container due to fire hazard caused by sparks and hot metal