## ~ Pax 7ip ~

## **Maple Top Maintenance**

- Maple tops are sealed and finished at the factory; should it be necessary to drill holes, make cut outs or cut through the sealed surface in any way, it is important that the altered area be re-sealed immediately: failure to do so may cause a drying-out process to occur which can result in separation of the wood fiber or glue joints • Clean with water, mild soap or detergent; after wiping clean, surface should
- Water should never be allowed to stand on the surface Maple is an organic product, and will react and adjust to the environment;

be dried thoroughly

excessive dryness or high humidity may cause a natural reaction in the form of small cracks in the surface which should be filled immediately without cause for alarm